

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD—
LOS ANGELES REGION

107 SOUTH BROADWAY, SUITE 4027
LOS ANGELES, CALIFORNIA 90012-4596
(213) 620-4460



SFUND RECORDS CTR
2166-01055

October 21, 1985

SFUND RECORDS CTR
88130476

Mr. Christopher M. Andrews
Manager-Engineering Quality
Control & Facilities
Airwork Corporation
Millville, N.J. 08332

UNDERGROUND TANK PIPELINES LEAK-PACIFIC AIRMOTIVE CORPPORATION
(File No. 83-8) (ID # 915050061)

Reference is made to your letter dated July 29, 1985, transmitting Kennedy/Jenks Engineers Report on Spill Clean-Up Activities conducted at your facility located at 2940 North Hollywood Way, Burbank, California.

Based upon our review and evaluation of the information submitted in your report we find that:

1. The clean-up of contaminated soils in Area I onsite has been satisfactory completed, and no additional work is needed.
2. The North/West portions of Area II onsite, encompassing soil sampling locations 2-5, 2-8, 2-9, and 2-10, still shows significant concentrations of fuel hydrocarbons which ranged from 1,400 mg/kg to 10,300 mg/kg.

You are requested to develop a workplan with an appropriate time schedule to determine the vertical extent of the soil contaminations remaining in Area II. In addition, an evaluation must be made to determine the rate of migration of the contamination.

Your workplan is due to this Regional Board by November 11, 1985. If you have any questions concerning this matter please contact me at (213) 620-5662 or Mr. David Bacharowski at (213) 620-5647.

JOSHUA M. WORKMAN
Senior Water Resource
Control Engineer

DAB:mp

cc: Mr. Lerner, Kennedy/Jenks Engineers
Mr. Wettstein, Pacific Airmotive Corporation